



COATING INSTRUCTIONS

Product: UT100 Two-Pack Acrylic Urethane Top Coat

- Step 1:** Wax & Grease remover for cleaning. Using a clean rag damp the rag slightly with wax & grease and wipe over the surface. Be sure to dry with another clean rag.
- Step 2:** Apply BC 300 clear etch primer (optional) mixed 1:1:1 with BC 300 etch hardener and BC 300 etch thinner. Spray two thin very light coats.
- Step 3:** Apply top coat using UT100 clear satin. Mix 4:1 with UT100 hardener and 10% UT100 thinner. Apply two - three medium coats. Allow minimum overnight to dry. Ensure to check dryness before packing.

Refer Technical Data Sheet for full product information.

Unit 7
13 Lyell Street
MITTAGONG NSW 2575

02 4872 2441

info@thatmetalcompany.com.au
www.thatmetalcompany.com.au